



I-91 TECH CENTER - BUILDING 2  
845 BROOK STREET  
ROCKY HILL, CONNECTICUT 06067  
PHONE: 203-257-3320 • FAX 203-257-3689



SEMS DocID 630133

NAME: OLIN CORP  
ID. NO.: CTD052544376  
FILE LOC: R-5  
OTHER: L 475 Smith St. 7

January 24, 1992

Sharon Hayes  
Work Assignment Manager (WAM)  
U.S. EPA Region I  
Superfund Support Section (HSS-CAN-7)  
John F. Kennedy Federal Building  
Boston, Massachusetts 02203-2211

Contract #68-W9-0018  
Work Order #4100-11-34  
Work Assignment #11-1JZZ

Subject: Tri-Star Sports, Inc. Visual Site Inspection (VSI)

Dear Ms. Hayes,

Enclosed please find:

- 1) A Trip Report from the January 20, 1992 visual site inspection (VSI) of Tri-Star Sports, Inc.
- 2) A site sketch illustrating major areas of the facility. An updated site sketch will be submitted with the Preliminary Assessment Plus draft report.

Sincerely,

ROY F. WESTON, INC.

John H. Insall  
Project Manager

cc: Jane Anderson, U.S. EPA (SAM)  
Joe Mastone, WESTON/ARCS  
Ernest Waterman, U.S. EPA



I-91 TECH CENTER - BUILDING 2  
845 BROOK STREET  
ROCKY HILL, CONNECTICUT 06067  
PHONE: 203-257-3320 • FAX 203-257-3689

January 24, 1992

Doug Zimmerman  
Superfund Site Assessment Contact  
State of Connecticut  
Department of Environmental Protection  
165 Capitol Avenue  
Hartford, Connecticut 06106

Contract #68-W9-0018  
Work Order #4100-11-34  
Work Assignment #11-1JZZ

Subject: Tri-Star Sports, Inc. Visual Site Inspection (VSI)

Dear Mr. Zimmerman,

Enclosed please find:

- 1) A Trip Report from the January 20, 1992 Visual Site Inspection (VSI) of Tri-Star Sports, Inc.
- 2) A site sketch illustrating major areas of the facility. An updated site sketch will be submitted with the draft Preliminary Assessment Plus draft report.

Sincerely,

ROY F. WESTON, INC.

John H. Insall  
Task Manager

cc: Sharon Hayes, U.S. EPA (WAM)  
Jane Anderson, U.S. EPA (SAM)  
Ernest Waterman, U.S. EPA  
Doug Zimmerman, State RCRA Contract

**To:** Jane Anderson/EPA (SAM)

**Date:** January 24, 1992

**From:** John Insall/WESTON

**Thru:** Joe Mastone

**Subject:** Trip Report-On Site Reconnaissance  
Tri-Star Sports, Inc.  
Middletown, Connecticut  
Work Assignment # 11-1JZZ  
TDD # 9108-34-AWE  
CERCLIS No. CTD0052544376

On January 20, 1992 Roy F. Weston (WESTON) staff conducted a Visual Site Inspection (VSI) at Tri-Star Sports, Inc. (TSS) in Middletown, Connecticut.


The on-site reconnaissance was conducted to identify Solid Waste Management Units (SWMU's), Areas of Concern (AOC's) present at the site, to obtain information on the operational history of the company and to assess the likelihood of releases of hazardous materials from the site.

John Insall (WESTON) arrived at TSS at 0900 hours and was escorted at the plant by Paul Short Environmental Engineer for Olin, Inc., the parent company of Tri-Star Sports. Photographs of the site were taken and will be submitted with the final report. Measurements of the areal extent of AOC's and SWMU's were obtained by WESTON representatives.

Nine AOC's were identified during the VSI and are illustrated on Figure 1. These areas include:

- NPDES outfall point
- Former Spill Containment Tank
- Raw Materials Storage Area
- Platen Room/Materials Storage
- Trench and Sump in Sanding Room
- Non Hazardous Waste Storage Area
- Painting Pit in Painting Area
- Trench and Sump in Grinding Room
- Fill Area in Parking Lot

The site inspection concluded at 1200 hours. All areas of the property were included in the inspection with the exception of one small office and a closet, which were locked at the time of the VSI.



SYMBOL	DESCRIPTION
HW	Hazardous Waste Storage Area
NHW	Non-Hazardous Waste Storage
RM	Raw Materials Storage Area
PP	Painting Pit
S	Sump
G	Grinding Area
SD	Sanding Area
VD	Vapor Degreaser

**SITE SKETCH**  
**Tri-Star Sports, Inc.**  
**Middletown, Connecticut**

not to scale